

<b>Project No.</b>	<b>Client</b>	<b>Location</b>	<b>Boring No.</b>	<b>Monitoring Well No.</b>	<b>Date</b>
01105	Metro Car Wash	2950 Harbor, CM	CB-6	N/A	August 10, 2005
<b>PID</b>	<b>BLOWS/ft. Sampler</b>	<b>DEPTH in feet</b>	<b>USCS Designation &amp; Soil Type</b>	<b>Color</b>	<b>Secondary Characteristics</b>
0	6-8-10	5	CL-Sandy Clay	Dark Grey	Stiff, Sl Damp, No Odor
0	8-10-14	10		Brown to Dark Brown	Dry
0	12-14-16	15	SM-Silty Sand	Brown	M. Dense, Sl Damp
0	12-14-18	20		Olive to Brown	
0	10-12-14	25	CL-Silty Clay	Brown	Stiff
0	9-15-22	30			
0	11-13-19	35			
0	8-14-17	40			
0	9-10-19	45	SM-Silty Sand	Tan	Dense, Damp, No Odor
0	12-16-25	50			
0	15-19-23	55			Moist
0	11-15-19	60			
0	12-14-15	65		Light Brown	
0	8-12-14	70			Wet
0	10-14-16	75	SP-Poorly Graded Sands	Tan	
<b>Field Engineer</b>	<b>Drilling Contractor</b>	<b>Drilling Foreman</b>	Boring terminated at 75 feet below grade. Groundwater at 67'. Boring backfilled with soil of origin and capped with bentonite plug (2'). Resurfaced with concrete		
M. Anselmo	J & H	Conrad			